

Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.

Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- Resolved Caveats - Cisco IOS XE Dublin 17.11.1a, on page 1
- Open Caveats - Cisco IOS XE Dublin 17.11.1a, on page 2
- Cisco Bug Search Tool, on page 3

Resolved Caveats - Cisco IOS XE Dublin 17.11.1a

Identifier	Headline
CSCwc80493	APS - K2 byte not reflecting proper value during LRDI and LAIS conditions.
CSCwd87661	Router Fan running at high speed and creating noise(Fan PID A903-FAN-H) - SW version 17.03.04
CSCwd16666	Ony in 3GMS OC3 port with network loop Bert pattern is not syncing
CSCwd40951	Cem getting removed successfully even with wrong T1 number provided from same T3/E3
CSCwd66728	ASR903-RSP-3C - uea_mgr crash seen with uea_brcm_update_hw_stats
CSCwd38074	Alarm reporting to IOS and L-bit propagation missing with STS-1E, CT-3, and E1 mode

Identifier	Headline
CSCwe19162	ASR903:RSP3: After SSO: False Alarm on CNAAP
CSCwd11926	Need support for dual options in CLI for setting clock rate for x21
CSCwd09785	Overhead DCC tunnel pseudowire not working in port 8 of NCS4200-1T8S-10CS
CSCwc41115	APS 1+1 Uni - Tx K2 to reflect Rx K1 channel number
CSCwd28121	STS-1E & CT-3;E1 loopback syslog and alarm reporting issues
CSCwd28107	RSP3: Bundle rommon version 15.6(57r)S to polaris_dev
CSCwc65971	RSP3: MPLS pseudowirte - Incorrect label stack pushed to packet
CSCwd05100	IM booting up on unsupported slot
CSCwd04198	A900-IMASER14A/S: when configurations are pasted in a specific order, line config is missing
CSCwd16099	Not able to unconfigure channel-group under STS-48c when 192 STS are used
CSCwd26330	IMA3G does not generate FEBE's when BPV, P-bit, C-bit error are detected on the T3 port
CSCwd48164	EVPN statd resource leak after protocol flaps
CSCwd44817	After router reload E1 framing gets changed to unframed in SDH VC12 mode with channe-group config
CSCwc10211	IMSG: Random VT's are down with LP_AIS due to Peer IMOIR with scale config with AU-4/tug-3/vc11-T1
CSCwe13024	ASR900-RSP2: All readings for Power supply unit reflect as zero though the unit is functional
CSCwd67723	In IMA32D/IMA8D card, sometimes change in E1 controller config(after ctrlr flap) results in IM reboot
CSCwd26357	rs485 with half-duplex configuration when reloaded, it gets into default full-duplex mode
CSCwd86980	High traffic drop is observed on RPFO
CSCwb68238	CSPN SSH requirement

Open Caveats - Cisco IOS XE Dublin 17.11.1a

Identifier	Headline
CSCwd88680	High Convergence after Port channel member failure.

Identifier	Headline
CSCwd05362	Performance issue on router platform.
CSCwe42290	Netconf intermittent connection issue due to checksum issue.
CSCwe34672	High CPU on ptp_uea process.
CSCwe33848	RSP3: Micro-bfd failed when trunk EFP is configured on the port channel

Cisco Bug Search Tool

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at http://www.cisco.com/web/applicat/cbsshelp/help.html