

Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The "Open Caveats" sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The "Resolved Caveats" sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.

Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- Open Caveats - Cisco IOS XE 17.13.1, on page 1
- Resolved Caveats - Cisco IOS XE 17.13.1, on page 1
- Cisco Bug Search Tool, on page 2

Open Caveats - Cisco IOS XE 17.13.1

Identifier	Headline
CSCwh85621	ASR 903 Layer 2 CEF interface is unavailable.
CSCwh80239	ASR900 RSP3 - IP SLA multicast configuration is not working.

Resolved Caveats - Cisco IOS XE 17.13.1

Identifier	Headline
CSCwf14167	RSP3: uea_mgr memory leak on ARP probes
CSCwf27439	IMD timer value update for ISSU process

Identifier	Headline
CSCwf90667	ASR903:IMA8Z:frequent reloads of IM due to high temp- FAN speed mismatch
CSCwf42164	No snmp trap link-status get re-added after IM reload
CSCwe82657	VIN P2/0, VOUT P2/2, VIN P4/0 & VOUT P4/2 alarms upon SSO
CSCwf77276	ASR903: memory leak seen on chunk module when BDI routed network traffic flow along with mac move
CSCwf49426	PAIS alarm get reported after IM OIR.
CSCwf77316	ASR900/RSP3: MPLS incorrect label programmed with scenarios of double implicit-null
CSCwf69937	The portchannel does not come up on adding recommended configs till we reload the router
CSCwf18367	RSP3 : uea_mgr RIFID leak/comsumption for Muticast routes
CSCwf07736	cem interface counters momentarily report error when x21 xconnect is cleared and re-established
CSCwh42209	RSS memory increment continuously seen uea_mgr process upon system event
CSCwf54249	With CPG, STS1e configuration is giving %ERROR: Standby doesn't support this command
CSCwf86864	CEM traffic flow is dropped in one direction due to DEI bit set from 4202
CSCwf37941	ACL config under serial interface makes dut crash during unconfig
CSCwh30217	A900-IMA3G-IMSG: With rate of OC12 we see "threshold sf-ber 3" getting added under sh run

Cisco Bug Search Tool

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at http://www.cisco.com/web/applicat/cbsshelp/help.html