

August 2024

- What's New in this Release, on page 1
- What's Changed in this Release, on page 1
- Issues, on page 2

What's New in this Release

The following new release is introduced in Cisco Spaces:

Location Service Release 3.1.0.156

The new features introduced are:

- Support for UWB AP to AP ranging for Cisco Catalyst 9800 Series Wireless Controller, Cisco IOS XE 17.15.1
- Enhancements to the Cisco Spaces: Connector connectivity test to include Netconf connection
- Addressed the following issues:
  - Data drop issue caused by duplicate connection and a corner case when there is large volumes of traffic
  - Local Firehose data drop issue caused by the publisher
  - Security issue where Cisco Catalyst 9800 Series Wireless Controller credentials are printed in the Cisco Spaces: Connector logs
  - Air pressure data collection issue for AP AnyLocate feature

What's Changed in this Release

The following enhancements are made in the Cisco Spaces dashboard:

This release enhances the performance of Cisco Spaces by optimising backend operations, thereby improving reliability and efficiency. It also includes upgrades to platform libraries to address issue fixes.

The performance enhancements include optimization of:

- Mapservice Integration APIs

- Map import process
- Digitization Stats

Issues

Issues describe unexpected behavior in the Cisco Spaces application.

Open Issues

This section lists the open issues in this release of Cisco Spaces.

Table 1: Cisco Spaces Open Issues

Issue Identifier	Issue Description
CSCwk97830	Hotspot 3.1 - The DNS configuration for Hotspot 3.1 is being removed when updating the OpenRoaming profile.

Resolved Issues

This section lists the issues that have been resolved in this release of Cisco Spaces.

Table 2: Cisco Spaces Resolved Issues

Issue Identifier	Issue Description
CSCwj71573	Controller status shows as "Degraded" under Connector, but "Active" under Controller