

February 2026

- What's New in this Release, on page 1
- What's Changed in this Release, on page 1
- Issues, on page 2

What's New in this Release

This new feature is introduced in Cisco Spaces:

Location Service

The Location Service Release 3.2.3.33 introduces support for the new UWN TDOA TDL, specifically targeting Cisco Catalyst 9800 Series Wireless Controller version 17.18.2.

What's Changed in this Release

These enhancements are made in Cisco Spaces.

Cisco Spaces Dashboard

These enhancements are made in the Cisco Spaces dashboard.

Error Boundary Enhancements

The Cisco Spaces Dashboard is enhanced to support a more reliable and seamless dashboard experience. These enhancements ensure smoother navigation, faster recovery, and greater confidence in using the dashboard.

- **Improve stability**: When a module encounters an unexpected error, the dashboard shows a recovery screen instead of crashing the entire page.
- **Isolate errors automatically**: Errors in one section, such as Maps or Smart Rooms, do not affect other sections. Only the module with the issue displays an error message.
- **Enable one-click recovery**: You can retry or navigate away from a failed module without refreshing the browser.
- **Increase error visibility**: The system automatically captures and logs unhandled errors and failed page loads. This helps us quickly identify and fix issues.

Zone Enhancements

Prior to this release, zone creation was supported only for 2D network maps generated directly from location data. With this release, zone creation capabilities are extended to cover 2D maps derived from rich maps.

You can now seamlessly draw and manage zone locations on these maps, ensuring consistent functionality across both network maps and CAD-derived rich maps.

Location Service

These enhancements are made in the Location Service Release 3.2.3.33.

- Updated the formatting of FastLocate messages to ensure they are correctly captured and displayed within the MAC debug viewer.
- Fixed encryption and decryption failures on FIPS-enabled systems, which was identified as a secondary cause for memory leaks in FastLocate messaging.
- Enhanced TDL deletion when the controller is removed from the connector.

Issues

Issues describe unexpected behavior in the Cisco Spaces application.

Open Issues

This section lists the open issues in this release of Cisco Spaces.

Table 1: Cisco Spaces Open Issues

Issue Identifier	Issue Description
CSCwt11133	Webex devices tab in meeting room shows (0) and displays meeting room info instead of device details in the new spaces UI
CSCwt29350	Cannot Clear out Calendar Activation from Integrations tab
CSCwt27912	Hotspot Client Certificate Renewal Failure Causing Authentication Disruptions

Resolved Issues

This section lists the issues that have been resolved in this release of Cisco Spaces.

Table 2: Cisco Spaces Resolved Issues

Issue Identifier	Issue Description
CSCws82925	Meraki Integration syncs all non-Cisco Spaces tagged networks.
CSCwq91293	All WLCs on Spaces Dashboard showing as Inactive as Control channel going DOWN temporarily.
CSCwr69026	SJC Alpha Prod Cisco Spaces- Connector>Wireless>'Test Connectivity' Fails.