End-of-Sale and End-of-Life Announcement for the Cisco APIC-M3, APIC-L3 and SE-NODE-G2

© 2025 Cisco and/or its affiliates. All rights reserved.

Contents

Overview 3

End-of-life milestones 3

Product part numbers 4

Product migration options 8

For more information 8

© 2025 Cisco and/or its affiliates. All rights reserved.

Overview

EOL15070 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco APIC-M3, APIC-L3 and SE-NODE-G2. The last day to order the affected product(s) is October 30, 2023. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco APIC-M3, APIC-L3 and SE-NODE-G2

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	May 1, 2023
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 30, 2023
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 28, 2024
End of SW (CIMC Only) Maintenance Release Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	October 29, 2026
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	October 31, 2028
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	October 29, 2024
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 29, 2024
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	January 25, 2028

© 2025 Cisco and/or its affiliates. All rights reserved.

Milestone	Definition	Date
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 31, 2028

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
APIC-CLUSTER-L3	APIC Cluster - Large Configurations (> 1200 Edge Ports)	APIC-CLUSTER-L4	APIC Cluster - Large Configurations (> 1200 Edge Ports)	-
APIC-CLUSTER-M3	APIC Cluster - Medium Configurations (Up to 1200 Edge Ports)	APIC-CLUSTER-M4	APIC Cluster - Medium Configurations (Up to 1200 Edge Ports)	-
APIC-CLUSTER-XS	APIC Cluster with virtual APIC	There is currently no replacement product available for this product.	-	-
APIC-CPU-3106	1.7 GHz 3106/85W 8C/11MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
APIC-CPU-4110	2.1 GHz 4110/85W 8C/11MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
APIC-CPU-I4210	Intel 4210 2.2GHz/85W 10C/13.75MB DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
APIC-HD1T7K12N	1 TB 12G SAS 7.2K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
APIC-L3	APIC Appliance - Large Configuration(> 1200 EdgePorts)	APIC-L4	APIC Appliance - Lage Configuration(> 1200 EdgePorts)	-
APIC-L3=	APIC Appliance - Lage Configuration(> 1200 EdgePorts)	APIC-L4=	APIC Appliance - Lage Configuration(> 1200 EdgePorts)	-
APIC-M3	APIC Appliance - Medium	APIC-M4	APIC Appliance - Medium	-

© 2025 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
	Configuration(Upto 1200 EdgePorts)		Configuration(Upto 1200 EdgePorts)	
APIC-M3=	APIC Appliance - Medium Configuration(Upto 1200 EdgePorts)	APIC-M4=	APIC Appliance - Medium Configuration(Upto 1200 EdgePorts)	-
APIC-MR-X16G1RS-H	16GB DDR4-2666-MHz RDIMM/PC4-21300/single rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
APIC-MR-X16G1RT-H	16GB DDR4-2933-MHz RDIMM/1Rx4/1.2v	There is currently no replacement product available for this product.	-	-
APIC-MSTOR-M2	Mini Storage carrier for M.2 SATA/NVME (holds up to 2)	There is currently no replacement product available for this product.	-	-
APIC-MSTOR-SD	Mini Storage Carrier for SD (holds up to 2)	There is currently no replacement product available for this product.	-	-
APIC-NVME-HW-H1600	1.6TB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	-	-
APIC-PSU1-770W	770W power supply for USC C-Series	There is currently no replacement product available for this product.	-	-
APIC-PSU1-770W=	770W power supply for USC C-Series (SPARE)	There is currently no replacement product available for this product.	-	-
APIC-RAID-M5	Cisco 12G Modular RAID controller with 2GB cache	There is currently no replacement product available for this product.	-	-
APIC-SD-32G-S	32GB SD Card for UCS servers	There is currently no replacement product available for this product.	-	-

© 2025 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
APIC-SD19TB121XEV	1.9TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD19TB121XEV=	1.9TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD19TK1X-EV	1.9TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD19TK1X-EV=	1.9TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD38TB121XEV	3.8TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD38TB121XEV=	3.8TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD38TK1X-EV	3.8TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD38TK1X-EV=	3.8TB 2.5 inch Enterprise Value 12G SAS SSD	There is currently no replacement product available for this product.	-	-
APIC-SD400G123X-EP	400GB 2.5in Enterprise Performance 12G SAS SSD(3X endurance)	There is currently no replacement product available for this product.	-	-
APIC-SD800GK3X-EP	800GB 2.5in Enterprise Performance 12G SAS SSD(3X endurance)	There is currently no replacement product available for this product.	-	-
APIC-SD800GS3X-EP	800GB 2.5in Enterprise Performance 12G SAS SSD(3X endurance)	There is currently no replacement product available for this product.	-	-
APIC-SE-L3	ACI APIC Services Edge	There is currently	-	-

© 2025 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
	(L3)	no replacement product available for this product.		
APIC-SERVER-L3	APIC Appliance - Large Config. (> 1200 Edge Ports)	APIC-SERVER-L4	APIC Appliance - Large Config. (> 1200 Edge Ports)	-
APIC-SERVER-L3=	APIC Appliance - Large Configuratio (1200 Edge Ports) SPARE	APIC-SERVER-L4=	APIC Appliance - Large Config. (> 1200 Edge Ports)	-
APIC-SERVER-M3	APIC Appliance - Medium Configuration (Upto 1200 Edge Ports)	There is currently no replacement product available for this product.	-	-
APIC-SERVER-M3=	APIC Appliance - Medium (Upto 1200 Edge Ports) SPARE	There is currently no replacement product available for this product.	-	-
APIC-TPM2-002	Trusted Platform Module 2.0 for UCS servers	There is currently no replacement product available for this product.	-	-
APIC-USBFLSHB-16GB	UCS Servers 16GB Flash USB Drive	There is currently no replacement product available for this product.	-	-
SE-CL-L3	Service Engine Cluster - Performance	ND-CLUSTER-L4	Nexus Dashboard Cluster - Performance	-
SE-NODE-G2	Service Node	ND-NODE-L4	Nexus Dashboard Node	-
SE-NODE-G2=	Service Node Option	ND-NODE-L4=	Nexus Dashboard Node Spare	-

© 2025 Cisco and/or its affiliates. All rights reserved.

Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade -in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco APIC-M3, APIC-L3 and SE-NODE-G2 through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to: https://www.cisco.com/c/en/us/products/remanufactured.html.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **https://www.cisco.com/go/offices**.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA Cxx-xxxxxxx-xx 12/25

© 2025 Cisco and/or its affiliates. All rights reserved.