End-of-Sale and End-of-Life Announcement for the Cisco Select HCI M6 accessories

© 2026 Cisco and/or its affiliates. All rights reserved.

Contents

Overview 3

End-of-life milestones 3

Product part numbers 3

Product Migration Options 13

For more information 13

© 2026 Cisco and/or its affiliates. All rights reserved.

Overview

EOL15712 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select HCI M6 accessories. The last day to order the affected product(s) is September 29, 2025. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select HCI M6 accessories

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	June 30, 2025
End-of-Sale Date Accessory	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 29, 2025
Last Ship Date Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 28, 2025

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-ADGPU-240M6	C240M6 GPU Air Duct 2USFF/NVMe (for DW/FL only)	There is currently no migration product available for this product.	-	-
HCI-ADGPU-240M6=	C240M6 GPU Air Duct 2USFF/NVMe (for DW/FL only)	There is currently no migration product available for this product.	-	-
HCI-AOSAHV-SWK9M6	HCI AOS AHV SW	There is currently no migration product available for this product.	-	-
HCI-AOSESXI-SWK9M6	HCI AOS ESXI SW	There is currently no migration product available for this	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
		product.		
HCI-BZL-C220-M6	C220 M6 Security Bezel	There is currently no migration product available for this product.	-	-
HCI-BZL-C220-M6=	C220 M6 Security Bezel	There is currently no migration product available for this product.	-	-
HCI-BZL-C240-M6	C240 M6 Security Bezel	There is currently no migration product available for this product.	-	-
HCI-BZL-C240-M6=	C240 M6 Security Bezel	There is currently no migration product available for this product.	-	-
HCI-CMA-C220M6	Reversible CMA for C220 M6 ball bearing rail kit	There is currently no migration product available for this product.	-	-
HCI-CMA-C240M6	Reversible CMA for C240 M6 ball bearing rail kit	There is currently no migration product available for this product.	-	-
HCI-CPU-I5318S	Intel 5318S 2.1GHz/165W 24C/36MB DDR4 2933MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I6354	Intel 6354 3.0GHz/205W 18C/39MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I8352M	Intel 8352M 2.3GHz/185W 32C/48MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I8352S	Intel 8352S 2.2GHz/205W 32C/48MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I8352V	Intel 8352V 2.1GHz/195W 36C/54M DDR4 2933MHz	There is currently no migration product available for this product.	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-CPU-I8352Y	Intel 8352Y 2.2GHz/205W 32C/48MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I8358P	Intel 8358P 2.6GHz/240W 32C/48MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I8368	Intel 8368 2.4GHz/270W 38C/57MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-CPU-I8380	Intel 8380 2.3GHz/270W 40C/60MB DDR4 3200MHz	There is currently no migration product available for this product.	-	-
HCI-FI-64108-M6	Cisco Compute Hyperconverged Fabric Interconnect 64108	There is currently no migration product available for this product.	-	-
HCI-FI-6454-M6	Cisco Compute Hyperconverged Fabric Interconnect 6454	There is currently no migration product available for this product.	-	-
HCI-FI-6536-M6	Cisco Compute Hyperconverged Fabric Interconnect 6536	There is currently no migration product available for this product.	-	-
HCI-FI-MANAGED-M6	Deployment mode for Server Managed by FI	There is currently no migration product available for this product.	-	-
HCI-GPU-A10-M6	TESLA A10, PASSIVE, 150W, 24GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A10-M6=	TESLA A10, PASSIVE, 150W, 24GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A100-80M6	TESLA A100, PASSIVE, 300W, 80GB	There is currently no migration product available for this product.	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-GPU-A100-80M6=	TESLA A100, PASSIVE, 300W, 80GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A16-M6	NVIDIA A16 PCIE 250W 4X16GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A16-M6=	NVIDIA A16 PCIE 250W 4X16GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A30-M6	TESLA A30, PASSIVE, 180W, 24GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A30-M6=	TESLA A30, PASSIVE, 180W, 24GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A40-M6	TESLA A40 RTX, PASSIVE, 300W, 48GB	There is currently no migration product available for this product.	-	-
HCI-GPU-A40-M6=	TESLA A40 RTX, PASSIVE, 300W, 48GB	There is currently no migration product available for this product.	-	-
HCI-GPU-T4-16	NVIDIA T4 PCIE 75W 16GB	There is currently no migration product available for this product.	-	-
HCI-GPU-T4-16=	NVIDIA T4 PCIE 75W 16GB	There is currently no migration product available for this product.	-	-
HCI-GPURKIT-C220	GPU Riser Bracket assy kit C220 / C225 1U	There is currently no migration product available for this product.	-	-
HCI-GPURKIT-C220=	GPU Riser Bracket assy kit C220 / C225 1U	There is currently no migration product available for this product.	-	-
HCI-IMM-MANAGED-M6	Deployment mode for Server and FI Managed	There is currently no migration product available for this	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
	by Intersight	product.		
HCI-INT-SW02-M6	C220 and C240 M6 Chassis Intrusion Switch	There is currently no migration product available for this product.	-	-
HCI-IS-MANAGED-M6	Deployment mode for Standalone Server Managed by Intersight	There is currently no migration product available for this product.	-	-
HCI-L-6400-100G-M6	FI per port to connect to Nexus/Ethernet switch or C-series	There is currently no migration product available for this product.	-	-
HCI-L-6400-25G-M6	FI per port license to connect to X/C-Series or FEX	There is currently no migration product available for this product.	-	-
HCI-L-6400-25GC-M6	FI per port license to connect to C-Direct	There is currently no migration product available for this product.	-	-
HCI-M-V100-04	Cisco UCS VIC 1477 dual port 40/100G QSFP28 mLOM	There is currently no migration product available for this product.	-	-
HCI-M-V100-04=	Cisco UCS VIC 1477 dual port 40/100G QSFP28 mLOM	There is currently no migration product available for this product.	-	-
HCI-M-V25-04	Cisco UCS VIC 1467 quad port 10/25G SFP28 mLOM	There is currently no migration product available for this product.	-	-
HCI-M-V25-04=	Cisco UCS VIC 1467 quad port 25G SFP28 mLOM	There is currently no migration product available for this product.	-	-
HCI-M-V5D200GV2M6	Cisco VIC 15237 2x 40/100/200G mLOM C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-M-V5D200GV2M6=	Cisco VIC 15237 2x 40/100/200G mLOM C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-
HCI-M-V5Q50GV2-M6	Cisco VIC 15427 4x 10/25/50G mLOM C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-
HCI-M-V5Q50GV2-M6=	Cisco VIC 15427 4x 10/25/50G mLOM C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-
HCI-M2-HWRAID-M6	Cisco Boot optimized M.2 Raid controller	There is currently no migration product available for this product.	-	-
HCI-MLOM-M6	Cisco VIC Connectivity	There is currently no migration product available for this product.	-	-
HCI-O-ID10GC-M6	Intel X710T2LOCPV3G1L 2x10GbE RJ45 OCP3.0 NIC	There is currently no migration product available for this product.	-	-
HCI-O-ID10GC-M6=	Intel X710T2LOCPV3G1L 2x10GbE RJ45 OCP3.0 NIC	There is currently no migration product available for this product.	-	-
HCI-P-I8D100GF-M6	Cisco-Intel E810CQDA2 2x100 GbE QSFP28 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-I8D100GF-M6=	Cisco-Intel E810CQDA2 2x100 GbE QSFP28 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-I8D25GF-M6	Cisco-Intel E810XXVDA2 2x25/10 GbE SFP28 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-I8D25GF-M6=	Cisco-Intel E810XXVDA2 2x25/10 GbE SFP28 PCIe NIC	There is currently no migration product available for this product.	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-P-I8Q25GF-M6	Cisco-Intel E810XXVDA4L 4x25/10 GbE SFP28 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-I8Q25GF-M6=	Cisco-Intel E810XXVDA4L 4x25/10 GbE SFP28 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-ID10GC-M6	Cisco-Intel X710T2LG 2x10 GbE RJ45 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-ID10GC-M6=	Cisco-Intel X710T2LG 2x10 GbE RJ45 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-IQ10GC-M6	Cisco-Intel X710T4LG 4x10 GbE RJ45 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-IQ10GC-M6=	Cisco-Intel X710T4LG 4x10 GbE RJ45 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-MCD100GF-M6	Cisco-MLNX MCX623106AC-CDAT 2x100GbE QSFP56 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-MCD100GF-M6=	Cisco-MLNX MCX623106AC-CDAT 2x100GbE QSFP56 PCIe NIC	There is currently no migration product available for this product.	-	-
HCI-P-MDD100GF-M6	Cisco-MLNX MCX623106AS-CDAT 2x100GbE QSFP56 PCIe NIC	HCI-P-M6DD100GFO	NVIDIA OEM MCX623106AS-CDAT, 2x100 GbE QSFP56 PCIe No Crypto	-
HCI-P-MDD100GF-M6=	Cisco-MLNX MCX623106AS-CDAT 2x100GbE QSFP56 PCIe NIC	HCI-P-M6DD100GFO=	NVIDIA OEM MCX623106AS-CDAT, 2x100 GbE QSFP56 PCIe No Crypto	-
HCI-P-V5D200G-M6	Cisco VIC 15235 2x 40/100/200G PCIe C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-
HCI-P-V5D200G-M6=	Cisco VIC 15235 2x 40/100/200G PCIe C-	There is currently no migration product available for this	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
	Series w/Secure Boot	product.		
HCI-P-V5Q50G-M6	Cisco VIC 15425 4x 10/25/50G PCIe C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-
HCI-P-V5Q50G-M6=	Cisco VIC 15425 4x 10/25/50G PCIe C-Series w/Secure Boot	There is currently no migration product available for this product.	-	-
HCI-PCIE-C100-04	Cisco UCS VIC 1495 Dual Port 100G QSFP28 CNA PCIe	There is currently no migration product available for this product.	-	-
HCI-PCIE-C100-04=	Cisco UCS VIC 1495 Dual Port 100G QSFP28 CNA PCIe	There is currently no migration product available for this product.	-	-
HCI-PCIE-C25Q-04	Cisco UCS VIC 1455 Quad Port 10/25G SFP28 CNA PCIE	There is currently no migration product available for this product.	-	-
HCI-PCIE-C25Q-04=	Cisco UCS VIC 1455 Quad Port 10/25G SFP28 CNA PCIE	There is currently no migration product available for this product.	-	-
HCI-PCIE-M6	Third Party NIC Connectivity	There is currently no migration product available for this product.	-	-
HCI-PCIEID10GF-M6	Intel X710-DA2 dual-port 10G SFP+ NIC	There is currently no migration product available for this product.	-	-
HCI-PCIEID10GF-M6=	Intel X710-DA2 dual-port 10G SFP+ NIC	There is currently no migration product available for this product.	-	-
HCI-PCIEIQ10GF-M6	Intel X710 quad-port 10G SFP+ NIC	There is currently no migration product available for this product.	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-PCIEIQ10GF-M6=	Intel X710 quad-port 10G SFP+ NIC	There is currently no migration product available for this product.	-	-
HCI-PSU-6332-ACM6	UCS 6332/ 6454 Power Supply/100-240VAC	There is currently no migration product available for this product.	-	-
HCI-PSU-6332-DCM6	UCS 6332/ 6454/ 64108 Power Supply/-48VDC	There is currently no migration product available for this product.	-	-
HCI-PSU-64108ACM6	UCS 64108 Power Supply/100-240VAC	There is currently no migration product available for this product.	-	-
HCI-PSU-6536-ACM6	UCS 6536 Power Supply/AC 1100W PSU - Port Side Exhaust	There is currently no migration product available for this product.	-	-
HCI-PSU1-1050W-M6	UCS 1050W AC PSU Platinum (Not EU/UK Lot 9 Compliant)	There is currently no migration product available for this product.	-	-
HCI-PSU1-1600W-M6	UCS 1600W AC PSU Platinum (Not EU/UK Lot 9 Compliant)	There is currently no migration product available for this product.	-	-
HCI-PSU1-2300W-M6	Cisco UCS 2300W AC Power Supply for Rack Servers Titanium	There is currently no migration product available for this product.	-	-
HCI-PSUV21050DCM6	Cisco UCS 1050W - 48V DC Power Supply for Rack Server	There is currently no migration product available for this product.	-	-
HCI-RAIL-M6	Ball Bearing Rail Kit for C220 & C240 M6 rack servers	There is currently no migration product available for this product.	-	-
HCI-RAIL-M6=	Ball Bearing Rail Kit for C220 & C240 M6 rack servers	There is currently no migration product available for this product.	-	-
HCI-RIS1A-240M6	C240 M6 Riser1A; (x8;x16x, x8); StBkt;	There is currently no migration product available for this	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
	(CPU1)	product.		
HCI-RIS3A-240M6	C240 M6 Riser3A (x8;x8); StBkt; (CPU2)	There is currently no migration product available for this product.	-	-
HCI-RIS3C-240M6	C240 M6 Riser 3C	There is currently no migration product available for this product.	-	-
HCI-SAS-220M6	Cisco 12G SAS HBA for (16 drives) w/1U Brkt	There is currently no migration product available for this product.	-	-
HCI-SAS-240M6	Cisco 12G SAS HBA for(16 Drives) w/2U Brkt	There is currently no migration product available for this product.	-	-
HCI-TPM-002C-M6	TPM 2.0, TCG, FIPS140-2, CC EAL4+ Certified, for M6 servers	There is currently no migration product available for this product.	-	-
HCI-TPM-002C-M6=	TPM 2.0, TCG, FIPS140-2, CC EAL4+ Certified, for M6 servers	There is currently no migration product available for this product.	-	-
HCI-TPM-002D-M6	TPM 2.0 TCG FIPS140-2 CC+ Cert M6 Intel MSW2022 Compliant	There is currently no migration product available for this product.	-	-
HCI-TPM-002D-M6=	TPM 2.0 TCG FIPS140-2 CC+ Cert M6 Intel MSW2022 Compliant	There is currently no migration product available for this product.	-	-
HCI-TPM-OPT-OUT-M6	OPT OUT, TPM 2.0, TCG, FIPS140-2, CC EAL4+ Certified	There is currently no migration product available for this product.	-	-
HCI-UCSM-MODE-M6	UCSM Deployment mode for FI	There is currently no migration product available for this product.	-	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
HCI-VIC-MODE-M6	HCI VIC Connectivity Mode	There is currently no migration product available for this product.	-	-

Product migration options

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **https://www.cisco.com/go/offices**.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA Cxx-xxxxxxx-xx 03/26

© 2026 Cisco and/or its affiliates. All rights reserved.