End-of-Sale and End-of-Life Announcement for the Cisco IR510 and IR530

© 2026 Cisco and/or its affiliates. All rights reserved.

Contents

Overview 3

End-of-life milestones 3

Product part numbers 4

Product migration options 5

For more information 5

© 2026 Cisco and/or its affiliates. All rights reserved.

Overview

EOL15791 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco IR510 and IR530. The last day to order the affected product(s) is May 1, 2026. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco IR510 and IR530

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 3, 2025
End-of-Sale Date: HW, OS SW, Accessory	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 1, 2026
Last Ship Date: HW, OS SW, Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 2, 2026
End of SW Maintenance Releases Date: HW, OS SW, Accessory	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 1, 2027
End of Vulnerability/Security Support: HW, Accessory	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	May 1, 2027
End of Routine Failure Analysis Date: HW, Accessory	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 1, 2027
End of New Service Attachment Date: HW, OS SW, Accessory	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 1, 2027
End of Service Contract Renewal Date: OS SW	The last date to extend or renew a service contract for the product.	July 30, 2028
End of Service Contract Renewal Date: HW, Accessory	The last date to extend or renew a service contract for the product.	July 30, 2030

© 2026 Cisco and/or its affiliates. All rights reserved.

Milestone	Definition	Date
Last Date of Support: OS SW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2029
Last Date of Support: HW, Accessory	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2031

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description
CAB-L240-15-Q-N	15-ft (4.6m) Low Loss LMR 240 Cable with QMA - N Connectors
CAB-L240-15-Q-N=	15-ft (4.6m) Low Loss LMR 240 Cable with QMA - N Connectors
IR500-H-BRKT	Horizontal Mounting Bracket for IR500
IR500-H-BRKT=	Horizontal Mounting Bracket for IR500
IR500-V-BRKT	Vertical mounting bracket for IR500
IR500-V-BRKT=	Vertical mounting bracket for IR500
IR510-DINRAIL	Din rail kit forIR510 915Mhz WPAN router
IR510-DINRAIL=	Din rail kit forIR510 915Mhz WPAN router
IR510-OFDM-ANZ/K9	IR510 915Mhz WPAN router Australia New Zealand
IR510-OFDM-BRZ/K9	IR510 915Mhz WPAN router Brazil
IR510-OFDM-FCC/K9	IR510 915Mhz WPAN router w/ 2 serial,1 FE LAN
IR530SB-OFD-ANZ/K9	IR530 915Mhz WPAN IP67 Range Ext. BBU Single antenna AUS NZ
IR530SB-OFD-BRZ/K9	IR530 915Mhz WPAN IP67 Range Ext. BBU Single antenna Brazil
IR530SB-OFD-FCC/K9	IR530 915Mhz WPAN IP67 Range Ext. BBU Adv PS Single antenna
IR510-COMPUTE-1.4	IR510 Software PID for compute module
SW-IR530WPAN-6.2	IR530 WPAN Software Release 6.2
SW-IR530WPAN-6.8	IR530 WPAN Software Release 6.8

© 2026 Cisco and/or its affiliates. All rights reserved.

Product migration options

There is no replacement available for the Cisco IR510 and IR530 at this time.

Customers may be able to use the Cisco Takeback and Reuse Program where applicable to return hardware that has reached end-of-use, at no cost. Returned products are put to their next best use, whether reused, remanufactured, or recycled by one of Cisco's certified contracted recyclers. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse.html.

Customers may be able to continue to purchase the Cisco IR510 and IR530 through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to: https://www.cisco.com/c/en/us/products/remanufactured.html.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **https://www.cisco.com/go/offices**.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA Cxx-xxxxxxx-xx 06/26

© 2026 Cisco and/or its affiliates. All rights reserved.