End-of-Sale and End-of-Life Announcement for the Cisco MDS 9700 Crossbar Switching Fabric-1 Module

© 2026 Cisco and/or its affiliates. All rights reserved.

Contents

Overview 3

End-of-life milestones 3

Product part numbers 4

Product migration options 6

For more information 7

© 2026 Cisco and/or its affiliates. All rights reserved.

Overview

EOL13606 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco MDS 9700 Crossbar Switching Fabric-1 Module. The last day to order the affected product(s) is September 30, 2021. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco MDS 9700 Crossbar Switching Fabric-1 Module

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	September 30, 2020
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 30, 2021
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 30, 2021
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	September 30, 2022
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	September 29, 2024
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	September 30, 2022
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 30, 2022
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	December 29, 2025

© 2026 Cisco and/or its affiliates. All rights reserved.

Milestone	Definition	Date
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 30, 2026

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Note: DS-X97-SF1-K9= and DS-X97-SF1-K9 are removed from this bulletin and are now part of EOL13605.

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
DS-C9706-1EK9	MDS 9706 32G Enhanced Config w/ Fans 2 Sup-1 6 Fab-1 4 PS	DS-C9706-V3K9	MDS 9706 V3 Config: Chassis, 2 Sup-4, 6 Fab-3, 4 3KAC	-
DS-C9706-1K9	MDS 9706 Base Config Chassis FANs 2 Sup-1 3 Fab-1 4 PS AC 3K	DS-C9706-V2K9	MDS 9706 V2 Base Config: Chassis, 2 Sup-4, 3 Fab-3, 2 3KAC	-
DS-C9706-2B8K9	MDS 9706 Bundle 2 16G LC 8GSFP 2Sup1 3 Fab1 4PS Ent Lic	There is currently no migration product available for this product.	-	-
DS-C9706-2BSK9	MDS 9706 Bundle 2 16G LC 16GSFP 2Sup1 3 Fab1 4PS Ent Lic	There is currently no migration product available for this product.	-	-
DS-C9706H-1K9	MDS 9710 Base Config HP Chassis FANs 2 Sup-1 3 Fab-1 4 PS 3K	There is currently no migration product available for this product.	-	-
DS-C9710-4B8K9	MDS 9710 Bundle 4 16G LC 8GSFP 2Sup1 3 Fab1 6PS Ent erP Lic	There is currently no migration product available for this product.	-	-
DS-C9710-4BSK9	MDS 9710 Bundle 4 16G LC 16GSFP 2Sup1 3 Fab1 6PS Ent erP Lic	There is currently no migration product available for this product.	-	-
DS-C9710H-1K9	MDS 9710 Base Config HP Chassis FANs 2 Sup-1 3 Fab-1 6 PS 3K	There is currently no migration product available for this product.	-	-
DS-C9718-1K9	MDS 9718 Base Config	DS-C9718-V3K9	MDS 9718 Config	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
	Chassis FAN 2 Sup1E 6 Fab-1 12 PS AC 3K		Chassis 2 Sup-4 6 Fab-3 and 8 3k AC PS	
DS-X9706-FAB1	MDS 9706 Crossbar Switching Fabric-1 Module	DS-X9706-FAB3	MDS 9706 Crossbar Switching Fabric-3 Module	-
DS-X9706-FAB1-D	MDS 9706 Crossbar Switching Fabric-1 Module	There is currently no migration product available for this product.	-	-
DS-X9706-FAB1-D=	MDS 9706 Crossbar Switching Fabric-1 Module	There is currently no migration product available for this product.	-	-
DS-X9706-FAB1=	MDS 9706 Crossbar Switching Fabric-1 Module	There is currently no migration product available for this product.	-	-
DS-X9706-FAB1B	MDS 9706 32G 3xFAB1 bundle	There is currently no migration product available for this product.	-	-
DS-X9706-FAB1B=	MDS 9706 Crossbar Switching Fabric-1 Module, Bundle of 3	There is currently no migration product available for this product.	-	-
DS-X9706H-FAB1=	MDS 9706 Crossbar Switching Fabric-1 Module for HP, Spare	DS-X9706-FAB3H=	MDS 9706 Crossbar Switching Fabric-3 Module HPE	-
DS-X9710-FAB1	MDS 9710 Crossbar Switching Fabric-1 Module	DS-X9710-FAB3	MDS 9710 Crossbar Switching Fabric-3 Module	-
DS-X9710-FAB1=	MDS 9710 Crossbar Switching Fabric-1 Module	There is currently no migration product available for this product.	-	-
DS-X9710-FAB1B	MDS 9710 32G 3xFAB1 bundle	There is currently no migration product available for this product.	-	-
DS-X9710-FAB1B=	MDS 9710 Crossbar Switching Fabric-1 Module, Bundle of 3	There is currently no migration product available for this product.	-	-
DS-X9710H-FAB1=	MDS 9710 Crossbar Switching Fabric-1 Module for HP, Spare	DS-X9710-FAB3H=	MDS 9710 Crossbar Switching Fabric-3 Module for HPE	-

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
DS-X9718-FAB1	MDS 9718 Crossbar Switching Fabric-1 Module	DS-X9718-FAB3	MDS 9718 Crossbar Switching Fabric-3 Module	-
DS-X9718-FAB1=	MDS 9718 Crossbar Switching Fabric-1 Module	There is currently no migration product available for this product.	-	-
DS-X9718-FAB1B=	MDS 9718 Crossbar Switching Fabric-1 Module, Bundle of 3	There is currently no migration product available for this product.	-	-
DS-C9710-1K9	MDS 9710 Base Config Chassis FANs 2 Sup-1 3 Fab-1 6 PS AC 3K	DS-C9710-V2K9	MDS 9710 V2 Base Config: Chassis, 2 Sup-4, 3 Fab-3, 4 3KAC	-
DS-C9710-1K9	MDS 9710 Base Config Chassis FANs 2 Sup-1 3 Fab-1 6 PS AC 3K	DS-C9710-V3K9	MDS 9710 V3 Config: Chassis, 2 Sup-4, 6 Fab-3,6 3KAC	-

Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco MDS 9700 Crossbar Switching Fabric-1 Module through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to: https://www.cisco.com/c/en/us/products/remanufactured.html.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html.

© 2026 Cisco and/or its affiliates. All rights reserved.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **https://www.cisco.com/go/offices**.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA Cxx-xxxxxxx-xx 05/26

© 2026 Cisco and/or its affiliates. All rights reserved.