End-of-Sale and End-of-Life Announcement for the Cisco HFC - Cisco Prisma Products

© 2026 Cisco and/or its affiliates. All rights reserved.

Contents

Overview 3

End-of-life milestones 3

Product part numbers 4

Product Migration Options 7

For more information 8

© 2026 Cisco and/or its affiliates. All rights reserved.

Overview

EOL14738 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco HFC - Cisco Prisma Products. The last day to order the affected product(s) is November 11, 2022. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco HFC - Cisco Prisma Products

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	May 13, 2022
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 11, 2022
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 9, 2023
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	November 11, 2023
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 11, 2023
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	February 6, 2027
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 30, 2027

HW = Hardware OS SW = Operating System Software App. SW = Application Software

© 2026 Cisco and/or its affiliates. All rights reserved.

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description
1005444	Prisma II XD PS,90-264VAC to -48VDC
4004497	(DCM-20-LL-SA)Low Insertion Loss DCF,20km,SA
4004498	(DCM-30-LL-SA)Low Insertion Loss DCF,30km,SA
4004499	(DCM-40-LL-SA)Low Insertion Loss DCF,40km,SA
4004500	(DCM-50-LL-SA)Low Insertion Loss DCF,50km,SA
4004669	(DCM-60-LL-SA)Low Insertion Loss DCF,60km,SA
4004670	(DCM-70-LL-SA)Low Insertion Loss DCF,70km,SA
4008281	(P2-HM)HD Host Module
4012717	(P2-HD-RXR-HG-SA)HD Dual Rev Rx,5-90MHz,HG,SA
4012718	(P2-HD-RXR-SA)HD Dual Rev Rx,5-90MHz,Std,SA
4013014	ICIM Terminator,DB9 Female
4016523	(P2-HD-RXF-SA)HD Fwd Rx,1GHz,SA
4022058	(P2-XD-CH-F)XD Chassis,F Conn
4022060	(P2-XD-ICIM)XD ICIM
4023066	Prisma II XD Chassis Blank Module
4023718	Prisma II XD Chassis DC Interconnect Cable
4023768	(P2-XD-CH-F-ICIM)XD Chassis,F Conn,ICIM
4037220	(P2-HD-EDFA-17-SA)1550HD EDFA Opt Amp,17dBm,SA
4037221	(P2-HD-EDFA-20-SA)1550HD EDFA Opt Amp,20dBm,SA
4037222	(P2-HD-EDFA-22-SA)1550HD EDFA Opt Amp,22dBm,SA
4037229	(P2-HD-OPSW-LA)1550HD Opt Switch,LA
4041277	EDR PRX85 Prisma HD Rx Module
4042697	P2-HD-EDFA-VGF-1X21-SA
4042750	EDR Rx OPM SR
4042751	EDR Rx OPM XR
CAB-TSTADPT-MCX-F=	Cable, Test Point Adapter MCX Conn to F
P2-EDFA-17L=	P2 HD low (5-9dB) gain single stage GF-EDFA; Sat Pow 17 dBm
P2-EDFA-21L=	P2 HD low (9-13dB) gain single stage GF-EDFA; Sat Pow 21 dBm
P2-HD-EDR-SA=	Prisma XD 2:1 EDR Transmitter
P2-RRX-LIN	PrismaII HD Dual Rev Rx, 5-300MHz, Low Input, SA
P2-RRX-STD	PrismaII HD Dual Rev Rx, 5-300MHz, Std Input, SA
P2-XD-CORD=	Prisma XD DC POWER CABLE 3M

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description
P2HD-FAN-ASSY=	P2 HD replacement fan assembly for P2-XD chassis
P2HD-HGEDR-PRX85	EDR with high gain; pluggable OPM Rx needed; 85 MHz BW
P2HD1.2G13TXP04=	P2 HD 1310 nm Tx, Premium, 4 dBm, SC/APC
P2HD1.2G13TXP06=	P2 HD 1310 nm Tx, Premium, 6 dBm, SC/APC
P2HD1.2G13TXP08=	P2 HD 1310 nm Tx, Premium, 8 dBm, SC/APC
P2HD1.2G13TXP10=	P2 HD 1310 nm Tx, Premium, 10 dBm, SC/APC
P2HD1.2G13TXP12=	P2 HD 1310 nm Tx, Premium, 12 dBm, SC/APC
P2HD1.2G13TXP14=	P2 HD 1310 nm Tx, Premium, 14 dBm, SC/APC
P2HD1.2G13TXP15=	P2 HD 1310 nm Tx, Premium, 15 dBm, SC/APC
P2HD1.2G13TXS03=	P2 HD 1310 nm Tx, Standard, 3 dBm, SC/APC
P2HD1.2G13TXS05=	P2 HD 1310 nm Tx, Standard, 5 dBm, SC/APC
P2HD1.2G13TXS06=	P2 HD 1310 nm Tx, Standard, 6 dBm, SC/APC
P2HD1.2G13TXS08=	P2 HD 1310 nm Tx, Standard, 8 dBm, SC/APC
P2HD1.2G13TXS10=	DO NOT ORDER - use P2HD1.2G13TXP10= at same price
P2HD1.2G13TXS12=	DO NOT ORDER - use P2HD1.2G13TXP12= at same price
P2HD1.2G15TXM21I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU21, SC/APC
P2HD1.2G15TXM22I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU22, SC/APC
P2HD1.2G15TXM24I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU24, SC/APC
P2HD1.2G15TXM26I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU26, SC/APC
P2HD1.2G15TXM28I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU28, SC/APC
P2HD1.2G15TXM33I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU33, SC/APC
P2HD1.2G15TXM36I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU36, SC/APC
P2HD1.2G15TXM39I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU39, SC/APC
P2HD1.2G15TXM44I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU44, SC/APC
P2HD1.2G15TXM48I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU48, SC/APC
P2HD1.2G15TXM52I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU52, SC/APC
P2HD1.2G15TXM54I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU54, SC/APC
P2HD1.2G15TXM57I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU57, SC/APC
P2HD1.2G15TXM60I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU60, SC/APC
P2HD1.2G15TXM61I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU61, SC/APC
P2HD1.2G15TXM62I=	P2 HD LRMW 1.2 GHz Tx, iWDM-ITU62, SC/APC
P2HD1.2G15TXQ20=	P2 HD SQAM 1.2 GHz Tx, ITU20, SC/APC
P2HD1.2G15TXQ21I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU21, SC/APC
P2HD1.2G15TXQ22I=	P2 HD SQAM 1.2 GHz Tx,iWDM- ITU22, SC/APC
P2HD1.2G15TXQ23=	P2 HD SQAM 1.2 GHz Tx, ITU23, SC/APC

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description
P2HD1.2G15TXQ24I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU24, SC/APC
P2HD1.2G15TXQ25=	P2 HD SQAM 1.2 GHz Tx, ITU25, SC/APC
P2HD1.2G15TXQ26I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU26, SC/APC
P2HD1.2G15TXQ27=	P2 HD SQAM 1.2 GHz Tx, ITU27, SC/APC
P2HD1.2G15TXQ28I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU28, SC/APC
P2HD1.2G15TXQ29=	P2 HD SQAM 1.2 GHz Tx, ITU29, SC/APC
P2HD1.2G15TXQ30=	P2 HD SQAM 1.2 GHz Tx, ITU30, SC/APC
P2HD1.2G15TXQ31=	P2 HD SQAM 1.2 GHz Tx, ITU31, SC/APC
P2HD1.2G15TXQ32=	P2 HD SQAM 1.2 GHz Tx, ITU32, SC/APC
P2HD1.2G15TXQ33I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU33, SC/APC
P2HD1.2G15TXQ34=	P2 HD SQAM 1.2 GHz Tx, ITU34, SC/APC
P2HD1.2G15TXQ35=	P2 HD SQAM 1.2 GHz Tx, ITU35, SC/APC
P2HD1.2G15TXQ36I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU36, SC/APC
P2HD1.2G15TXQ37=	P2 HD SQAM 1.2 GHz Tx, ITU37, SC/APC
P2HD1.2G15TXQ38=	P2 HD SQAM 1.2 GHz Tx, ITU38, SC/APC
P2HD1.2G15TXQ39I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU39, SC/APC
P2HD1.2G15TXQ40=	P2 HD SQAM 1.2 GHz Tx, ITU40, SC/APC
P2HD1.2G15TXQ41=	P2 HD SQAM 1.2 GHz Tx, ITU41, SC/APC
P2HD1.2G15TXQ42=	P2 HD SQAM 1.2 GHz Tx, ITU42, SC/APC
P2HD1.2G15TXQ43=	P2 HD SQAM 1.2 GHz Tx, ITU43, SC/APC
P2HD1.2G15TXQ44I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU44, SC/APC
P2HD1.2G15TXQ45=	P2 HD SQAM 1.2 GHz Tx, ITU45, SC/APC
P2HD1.2G15TXQ46=	P2 HD SQAM 1.2 GHz Tx, ITU46, SC/APC
P2HD1.2G15TXQ47=	P2 HD SQAM 1.2 GHz Tx, ITU47, SC/APC
P2HD1.2G15TXQ48I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU48, SC/APC
P2HD1.2G15TXQ49=	P2 HD SQAM 1.2 GHz Tx, ITU49, SC/APC
P2HD1.2G15TXQ50=	P2 HD SQAM 1.2 GHz Tx, ITU50, SC/APC
P2HD1.2G15TXQ51=	P2 HD SQAM 1.2 GHz Tx, ITU51, SC/APC
P2HD1.2G15TXQ52I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU52, SC/APC
P2HD1.2G15TXQ53=	P2 HD SQAM 1.2 GHz Tx, ITU53, SC/APC
P2HD1.2G15TXQ54I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU54, SC/APC
P2HD1.2G15TXQ55=	P2 HD SQAM 1.2 GHz Tx, ITU55, SC/APC
P2HD1.2G15TXQ56=	P2 HD SQAM 1.2 GHz Tx, ITU56, SC/APC
P2HD1.2G15TXQ57I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU57, SC/APC
P2HD1.2G15TXQ58=	P2 HD SQAM 1.2 GHz Tx, ITU58, SC/APC

© 2026 Cisco and/or its affiliates. All rights reserved.

End-of-Sale Product Part Number	Product Description
P2HD1.2G15TXQ59=	P2 HD SQAM 1.2 GHz Tx, ITU59, SC/APC
P2HD1.2G15TXQ60I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU60, SC/APC
P2HD1.2G15TXQ61I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU61, SC/APC
P2HD1.2G15TXQ62I=	P2 HD SQAM 1.2 GHz Tx, iWDM-ITU62, SC/APC
P2HD1.2G15TXQP21I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU21, SC/APC
P2HD1.2G15TXQP22I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU22, SC/APC
P2HD1.2G15TXQP24I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU24, SC/APC
P2HD1.2G15TXQP26I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU26, SC/APC
P2HD1.2G15TXQP28I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU28, SC/APC
P2HD1.2G15TXQP33I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU33, SC/APC
P2HD1.2G15TXQP36I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU36, SC/APC
P2HD1.2G15TXQP39I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU39, SC/APC
P2HD1.2G15TXQP44I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU44, SC/APC
P2HD1.2G15TXQP48I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU48, SC/APC
P2HD1.2G15TXQP52I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU52, SC/APC
P2HD1.2G15TXQP54I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU54, SC/APC
P2HD1.2G15TXQP57I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU57, SC/APC
P2HD1.2G15TXQP60I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU60, SC/APC
P2HD1.2G15TXQP61I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU61, SC/APC
P2HD1.2G15TXQP62I=	P2 HD HQT 1.2 GHz Tx, iWDM-ITU62, SC/APC
4043499	P2-HD-EDFA-VGF-1X17-SA

Product Migration Options

There is no replacement available for the Cisco HFC - Cisco Prisma Products at this time.

Customers may be able to use the Cisco Takeback and Reuse Program where applicable to return hardware that has reached end-of-use, at no cost. Returned products are put to their next best use, whether reused, remanufactured, or recycled by one of Cisco's certified contracted recyclers. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse.html.

Customers may be able to continue to purchase the Cisco HFC - Cisco Prisma Products through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to: https://www.cisco.com/c/en/us/products/remanufactured.html.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html.

© 2026 Cisco and/or its affiliates. All rights reserved.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **https://www.cisco.com/go/offices**.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA Cxx-xxxxxxx-xx 08/26

© 2026 Cisco and/or its affiliates. All rights reserved.