

New and Changed Information

- New and Changed Information, on page 1

New and Changed Information

This table summarizes the new and changed features for the *Cisco Nexus 9000 Series NX-OS Troubleshooting Guide, Release 10.3(x)*.

Table 1: New and Changed Features

Feature	Description	Changed in Release	Where Documented
sFlow Consistency Checker	Added support for sFlow Consistency Checker on Cisco Nexus 9808 platform switches.	10.3(3)F	Consistency Checker Commands Using sFlow sFlow Consistency Checker
ITD Consistency Checker	Added support for ITD consistency checker on Cisco Nexus 9300-EX/FX/FX2/FX3/GX/GX2 platform switches.	10.3(2)F	ITD Consistency Checker
MPLS Consistency Checker	Proactive consistency checker will be supporting MPLS route consistency check.	10.3(2)F	Proactive Consistency Checker
Interface Consistency Checker	Added support for interface consistency checker on Cisco Nexus 9808 platform switches.	10.3(1)F	Interface Consistency Checker
ACL Consistency Checker	Added support for ACL consistency checker on Cisco Nexus 9808 platform switches.	10.3(1)F	ACL Consistency Checker

Feature	Description	Changed in Release	Where Documented
Counter to show techs for ASICS	Added CLIs for the **show tech-support module all** command.	10.3(1)F	Steps to Perform Before Calling TAC
Proactive Consistency Checker enhancement	Added support for Proactive Consistency Checker on Cisco Nexus 9504 and 9508 platform switches.	10.3(1)F	Proactive Consistency Checker
L3 Consistency Checker	Added support for L3 Consistency Checker on Cisco Nexus 9808 platform switches.	10.3(1)F	Consistency Checker Commands
Commands to run statistics on all modules	Added new commands to display statistics from all the modules.	10.3(1)F	Packet Flow Issues
Command to run Hardware Statistics	Added a new command to collect hardware statistics from all the slots.	10.3(1)F	Steps to Perform Before Calling TAC
Ethanalyzer	Added support for Ethanalyzer on Cisco Nexus 9808 platform switches.	10.3(1)F	Using Ethanalyzer