

Cisco Intersight Managed Mode Infrastructure Firmware, Release 6.0

- Cisco Intersight Managed Mode Infrastructure Firmware, Release 6.0, on page 1
- Firmware Version Equivalency Between Cisco Intersight, Cisco IMC, and Cisco UCS Manager, on page 1
- Revision History, on page 2

Cisco Intersight Managed Mode Infrastructure Firmware, Release 6.0

Firmware upgrades in Intersight include server firmware upgrades and infrastructure firmware upgrades. Infrastructure firmware upgrades in Intersight Managed mode is supported on Cisco UCS Fabric Interconnects Series 6600, 6500, 6400, and Cisco UCS X-Series Direct Fabric Interconnects. To manage the Cisco UCS infrastructure firmware, see Upgrading Fabric Interconnect Firmware in IMM. This feature is available with a Cisco Intersight Essentials or Advanced license tier.

In Intersight, infrastructure and server firmware upgrades can be done independently. That is, you do not need to upgrade infrastructure firmware to use the latest server firmware and vice versa. For more information on compatibility between infrastructure firmware and server firmware, see Cross Version Firmware Support. For more information on server firmware updates, see Release Notes for Cisco Intersight Managed Mode Server Firmware.

Firmware Version Equivalency Between Cisco Intersight, Cisco IMC, and Cisco UCS Manager

For more information, see Cisco UCS Equivalency Matrix for Cisco Intersight, Cisco IMC, and Cisco UCS Manager.

To view the complete matrix in PDF format, click here.

Revision History

The following table includes the change history for this document.

Table 1: Release 6.0

Revision Date	Description
August 17, 2026	X-Series M8, M7 6.0(2.260180) and C-Series M8, M7 6.0(2.260180) Server Firmware versions have been released. There is no corresponding Infrastructure Firmware release.
July 14, 2026	B-Series M5 6.0(1.260031) Server Firmware version has been released. There is no corresponding Infrastructure Firmware release.
June 25, 2026	Updated release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure Firmware version 6.0(2.260067). This release includes updates to: • Resolved issues in Release 6.0(2.260067) It does not include any new hardware support, security fixes, or open issues.
April 23, 2026	Updated release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure Firmware version 6.0(2.260055). It does not include any new hardware features, security fixes, resolved issues, or open issues. Corresponding server firmware release notes have been updated for the following versions: X-Series M8, M7, M6 6.0(2.260069), C-Series M8, M7, M6 6.0(2.260069), and B-Series M6 6.0(2.260069). Cisco UCS X580p PCIe Node firmware version 6.0(2.260069) and Cisco UCS X9508 Chassis firmware version 6.0(2.260069) have been released.

Revision Date	Description
March 27, 2026	Updated release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure Firmware version 6.0(1.260006). This release includes updates to: • Resolved issues in Release 6.0(1.260006) It does not include any new hardware support, security fixes, or open issues.
March 16, 2026	B-Series M5 6.0(1.260012) Server Firmware version has been released. There is no corresponding Infrastructure Firmware release.
March 16, 2026	Updated release notes for Cisco UCS 6600, 6500, 6400 Series FI and Cisco UCS X-Series Direct FI Infrastructure Firmware version 6.0(2.260045). This release includes updates to: • New hardware features in 6.0(2.260045) • Resolved issues in Release 6.0(2.260045) • Open issues in Release 6.0(2.260045) • Known issues in Release 6.0(2.260045) It does not include any security fixes.
March 02, 2026	Included CSCwt36346 in Open issues in Release 6.0(1.250198)
February 06, 2026	Updated release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect Infrastructure firmware release 6.0(1.260003) and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure Firmware version 6.0(1.260003). This release includes updates to: • Resolved issues in Release 6.0(1.260003) It does not include any new hardware support, security fixes, or open issues.
January 14, 2026	C-Series M8 6.0(1.250194) Server Firmware version has been released. There is no corresponding Infrastructure Firmware release.

Revision Date	Description
December 18, 2025	Updated release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect Infrastructure firmware release 6.0(1.250243) and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure Firmware version 6.0(1.250243). It does not include any new hardware feature, security fixes, resolved issues, or open issues. Corresponding server firmware release notes have been updated for the following versions: X-Series M8 6.0(1.252114), M7, M6 6.0(1.250179), B-Series M6, M5 6.0(1.250169), and C-Series M8, M7, M6 6.0(1.250192). Cisco UCS X580p PCIe Node firmware version 6.0(1.252050) and Cisco UCS X9508 Chassis firmware version 6.0(1.252050) have been released.
December 12, 2025	Updated the following sections: • New hardware features in 6.0(1.250229) to include support for Cisco UCS X580p PCIe Node and Cisco UCS X9516 X-Fabric. • Open issues in Release 6.0(1.250229) to include CSCwr31737.
November 21, 2025	X-Series M8 6.0(1.252039) Server Firmware version has been released. There is no corresponding Infrastructure Firmware release.
November 12, 2025	Updated release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect Infrastructure firmware release 6.0(1.250229) and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure Firmware version 6.0(1.250229). It does not include any new hardware feature, security fixes, resolved issues, or open issues. Corresponding server firmware release notes have been updated for the following versions: X-Series M8, M7, M6 6.0(1.250162), B-Series M6, M5 6.0(1.250157), and C-Series M8, M7, M6 6.0(1.250174).
November 07, 2025	Added information on deprecated hardware.

Revision Date	Description
October 09, 2025	X-Series M8, M7, M6 6.0(1.250122), B-Series M6, M5 6.0(1.250127), and C-Series M8, M7, M6 6.0(1.250131) Server Firmware versions have been released. There is no corresponding Infrastructure Firmware release.
September 09, 2025	Added Cisco UCS NVMeoF Support Matrix for 3rd Party Storage Vendors matrix.
September 02, 2025	Created release notes for Cisco UCS 6600, 6500, and 6400 Series Fabric Interconnect Infrastructure firmware 6.0(1.250198) and Cisco UCS X-Series Direct Fabric Interconnect Infrastructure firmware 6.0(1.250198). This release includes updates to: • New hardware features in 6.0(1.250198) • Open issues in Release 6.0(1.250198) It does not include any security fixes or resolved issues.