

Intersight eCMC Infrastructure Software Bundle

- eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(2.260143), on page 1
- eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(2.260034), on page 1
- eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(2.260026), on page 2
- eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(1.251006), on page 2
- eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(1.251005), on page 3

eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(2.260143)

eCMC Infrastructure firmware bundle contains the following images for Cisco UCS XE9305:

Component	Packaged Version	Firmware Name
pdbFPGA	V202	pdbfpga.spi
CMC	6.0(2.260036)	cmc.img
PSU	1.6.0.0,3.5.0.0	qcs_psu.bin
eCMCFPGA	V200	ecmcfpga.spi
MTS	1.0.2.2	mts.bin
slamlatch	V24	slamlatch.upg

eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(2.260034)

eCMC Infrastructure firmware bundle contains the following images for Cisco UCS XE9305:

Component	Packaged Version	Firmware Name
pdbFPGA	V202	pdbfpga.spi

Component	Packaged Version	Firmware Name
CMC	6.0(2.260034)	cmc.img
PSU	1.6.0.0,3.5.0.0	qcs_psu.bin
eCMCFPGA	V200	ecmcfpga.spi
MTS	1.0.2.2	mts.bin
slamlatch	V24	slamlatch.upg

eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(2.260026)

eCMC Infrastructure firmware bundle contains the following images for Cisco UCS XE9305:

Component	Packaged Version	Firmware Name
pdbFPGA	V202	pdbfpga.spi
CMC	6.0(2.260026)	cmc.img
PSU	1.6.0.0,3.5.0.0	qcs_psu.bin
eCMCFPGA	V200	ecmcfpga.spi
MTS	1.0.2.2	mts.bin
slamlatch	V24	slamlatch.upg

eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(1.251006)

eCMC Infrastructure firmware bundle contains the following images for Cisco UCS XE9305:

Component	Packaged Version	Firmware Name
pdbFPGA	V202	pdbfpga.spi
CMC	6.0(1.251006)	cmc.img
PSU	1.5.0.0,3.4.0.0	qcs_psu.bin
eCMCFPGA	V200	ecmcfpga.spi
MTS	1.0.1.3	mts.bin

eCMC Infrastructure Firmware Bundle for Cisco UCS XE9305 6.0(1.251005)

eCMC Infrastructure firmware bundle contains the following images for Cisco UCS XE9305:

Component	Packaged Version	Firmware Name
pdbFPGA	V202	pdbfpga.spi
CMC	6.0(1.251005)	cmc.img
PSU	1.5.0.0,3.4.0.0	qcs_psu.bin
eCMCFPGA	V200	ecmcfpga.spi
MTS	1.0.1.3	mts.bin