

Release 3, May 2023

- What's New in Release 3, May 2023, on page 1
- Caveats, on page 1

What's New in Release 3, May 2023

This release supports all connector upgrades and service upgrades from Cisco Spaces dashboard.

This release includes the following features:

- **High Availability:** by configuring virtual IP address (VIP) for the connector instance pair.
- **IPv6:** is supported.

Note Connector IPv6 for IoT service (wireless) is supported on Cisco IOS XE 17.12.x

- **Dual-interface deployment:** of connector.
- **Local Firehose:** is supported.
- **System upgrade:** from Cisco Spaces is supported.
- **Hyper-V, AMI, and OVA**: deployment of connector.

Caveats

Open Caveats in Connector, Release 3, May 2023

Table 1: Open Caveats

Caveat	Description
CSCwf28869	Unable to SSH or login to AMI IPv6 instance
CSCwf28880	VIP address configuration fails with AMI connectors.

Caveat	Description
CSCwf27599	IoT Streams set up is unsuccessful on a day 0 High-Availability deployment.
CSCwf27095	After a successful upgrade of IoT service (wireless), wireless controller moves to a degraded state.
CSCwf31185	Fastlocate in High-Availability VIP Paired does not propagate SPI Keys to connector instances

Resolved Caveats in Connector, Release 3, May 2023

Table 2: Resolved Caveats

Caveat	Description
CSCwe29576	Location service is not automatically added to connector 3.