

Release 3, May 2024

- What's New in Release 3, May 2024, on page 1
- Issues , on page 2

What's New in Release 3, May 2024

This release includes the following features:

- **Vulnerability Fixes**: Fixes upto May 2024 are available.
- **New Commands Introduced**: Two new commands introduced.
  - The **connectorctl cert show-ca-cert** command shows the Certification Authority (CA) certificate installed.
  - The **connectorctl cert remove-ca-cert -s <Serial Number of Certificate>** command simplifies the removal of certificates by serial number.

  For detailed information, refer to the Cisco Spaces: Connector3 Command Reference Guide.
- **Validation Checks**: Cisco Catalyst 9800 Series Wireless Controllers or switches cannot not be added in the same subnet as the docker.
- **Modified Output**: The **connectorctl dockersubnet show** command now presents detailed information about configured subnets.
- **User Interface Enhancement**: The connector GUI now displays the docker service network.
- **IPv6 Support**: Configuration of IPv6 Virtual IP addresses (VIP) is now supported.
- **Privacy Settings API**: The privacy settings API is available for use. See Cisco Spaces API Guide . The updated URL is

  `https:<connector-ip>/api/connector/v1/privacy`

  .

Note To upgrade to Release 3 May 2024, see Upgrade Path for Release 3.

Issues

Resolved Issues in, Release 3, May 2024

Table 1: Resolved Issues

ID	Description
CSCwj89252	The service manager log `keepalived_ha.log` defaults to `root` owner and group.