

February 2024

- What's New in this Release, on page 1
- What's Changed in this Release, on page 1
- Issues, on page 2

What's New in this Release

The following new release is introduced in Cisco Spaces:

Local Firehose Service Release 3.1.0.65

The new features introduced are:

- Local Firehose Service opens up local firehose channel (gRPC) in Cisco Spaces: Connector 3 and sends out location updates for Aeroscout Location/BLE tags.
- Use the Cisco Spaces Partner app to consume location Received Signal Strength Indicator (RSSI) and Internet of Things (IoT) Bluetooth Low Energy (BLE) RSSI measurements over gRPC (Remote Procedure Call) channel.
- The Stanley Aeroscout Location Engine is succesfully integrated with Cisco Spaces: Connector 3.x. Refer to the *Securitas Document KB1100* article for more information.

Note For more information, see Cisco Spaces: Connector 3 Configuration Guide.

What's Changed in this Release

The following enhancements are made in Cisco Spaces:

Right Now App

The wired visitor count in the **Right Now** app is enhanced to automatically reset the visitor count to zero daily at 3 a.m., ensuring synchronization with the Location Hierarchy timezone settings.

Cisco Spaces: Location Services Release 3.1.0.127

The docker release focuses on the **AP AnyLocate** feature enhancements:

- The AP air pressure data issue in the Cisco Catalyst 9800 Series Wireless Controllers Cisco IOS XE 17.13.1 release is resolved. This enhancement improves the autoclustering of APs when placing them using the **AP AnyLocate** feature.
- Currently, the issue is addressed in Cisco IOS XE 17.12.3 release.
- Addressed the issue regarding unreliable AP FTM ranging measurement for 6-GHz radio with **AFC Standard Power mode** configuration enabled in the following Catalyst 9800 controller releases:
  - Cisco IOS XE Dublin 17.12.1
  - Cisco IOS XE Dublin 17.12.2
  - Cisco IOS XE 17.13.1

Note

- CSCwh98522 tracks the Catalyst 9800 controller issue.
- This issue does not impact upgrade from Catalyst 9800 controller Cisco IOS XE Dublin 17.12.1 or 17.12.2 to Cisco IOS XE Dublin 17.12.3.

Cisco Spaces: Connector 3 Service Manager Release 3.1.2.45

The following enhancements are made in **Service Manager**:

- New **connectorctl dockersubnet** command to support docker network change. For more information, see Cisco Spaces: Connector3 Command Reference Guide.
- Added NTP service monitoring and auto recovery services to check if the service is down.
- Enhanced keepalive event notifications and handlers for High Availability
- Enhanced privacy settings to exclude blank values for **MAC Username Salt**
- Addressed the Audit log permission issue during password reset.
- Enhancement is made in the AMI connector instance for Amazon Web Service (AWS) to share public IP address along with services.

Issues

Issues describe unexpected behavior in the Cisco Spaces application.

Open Issues

This section lists the open issues in this release of Cisco Spaces.

Table 1: Cisco Spaces Open Issues

Issue Identifier	Issue Description
CSCwi11258	Failed to delete Building from Map Services

Resolved Issues

This section lists the issues that have been resolved in this release of Cisco Spaces.

Table 2: Cisco Spaces Resolved Issues

Issue Identifier	Issue Description
CSCwj13626	Occupancy Report - In some case list page is not loading when user edits the locations in the report
CSCwj13870	User getting 'Invalid OTP' error when entering correct OTP
CSCwi92266	No response from RADIUS server. AAA timeout is being received at controller end