

July 2024

- What's New in this Release, on page 1
- What's Changed in this Release, on page 1
- Issues, on page 2

What's New in this Release

The following new release is introduced in Cisco Spaces:

Cisco Spaces: Connector 3 Service Manager Release 3.1.3.45

- Added Docker subnet mask validation for Service Network configuration
- Added retry attempts for Services download
- Enhanced the CLI output of **Userauth password** command

For more information, see Release Notes for Cisco Spaces: Connector.

What's Changed in this Release

Support for Bluetooth Low Energy (BLE) devices are now available on the Cisco Meraki network, in addition to the existing support on the Cisco Catalyst Wireless network.

This enhancement allows the Cisco Spaces platform to seamlessly integrate with BLE devices using Cisco Meraki. With this enhancement, Cisco Meraki BLE devices can now be accessed in various Cisco Spaces applications, including Firehose IoT Telemetry events, IoT Explorer, Signage, and RightNow.

Note For this feature to work, you must perform specific configurations on the Cisco Meraki network to enable the data transmission to Cisco Spaces. We recommend that you contact Cisco Spaces support team for further assistance.

Issues

Issues describe unexpected behavior in the Cisco Spaces application.

Open Issues

This section lists the open issues in this release of Cisco Spaces.

Table 1: Cisco Spaces Open Issues

Issue Identifier	Issue Description
CSCwj71573	Controller status shows as "Degraded" under Connector, but "Active" under Controller

Resolved Issues

This section lists the issues that have been resolved in this release of Cisco Spaces.

Table 2: Cisco Spaces Resolved Issues

Issue Identifier	Issue Description
CSCwk30773	Newly created Location Analytics reports are not appearing on list page until the page is refreshed
CSCwk12061	Captive Portal Runtime - Loading wrong default country on DC page